Serial Nr.: 10/627,837 03177-URS

Art Unit: 3729

### **AMENDMENTS TO THE DRAWINGS:**

### FIG. 1, amend the description in step 101 as follows:

choosing all the points to be tested on the [[print]] printed circuit board by software

# FIG. 1, amend the description in step 102 as follows:

making a ptint citeuit printed circuit board having protruding metal points

### FIG. 1, amend the description in step 103 as follows:

connecting all the metal points to holes for connection members located at a side of the [[print]] <u>printed</u> circuit board by way of layout

## FIG. 1, amend the description in step 106 as follows:

aligning the points to be tested on the [[print]] <u>printed</u> circuit board with the protruding metal points

### FIG. 1, amend the description in step 107 as follows:

using the pressure from the press of the tester to contact the protruding metal points and points to be tested on the [[print]] <u>printed</u> circuit board

### FIG. 2, amend the description in step 101 as follows:

choosing all the points to be tested on the [[print]] printed circuit board by software

### FIG. 2, amend the description in step 102 as follows:

making a ptint eiteuit printed circuit board having protruding metal points

### FIG. 2, amend the description in step 103 as follows:

connecting all the metal points to holes for connection members located at a side of the [[print]] <u>printed</u> circuit board by way of layout

# FIG. 2, amend the description in step 205 as follows:

inserting a pressure <u>inductive</u> <u>sensitive</u> conductive rubber layer between the protruding metal [[point]] <u>points</u> and the points to be tested on the [[print]] <u>printed</u> circuit board

#### FIG. 2, amend the description in step 206 as follows:

using the press of the tester to apply a pressure to the inductive pressure sensitive conductive rubber via the protruding metal [[point]] points and the points to be tested on the [[print]] printed circuit board to make them [[to be]] electrically connected

### FIG. 3, amend the description in step 101 as follows:

choosing all the points to be tested on the [[print]] printed circuit board by software

### FIG. 3, amend the description in step 102 as follows:

making a ptint citcuit printed circuit board having protruding metal points

### FIG. 3, amend the description in step 103 as follows:

connecting all the metal points to holes for connection members located at a side of the [[print]] <u>printed</u> circuit board by way of layout

### FIG. 3, amend the description in step 305 as follows:

connecting conductive rubber taping an electrically z-axis conductive adhesive film to a tip of each metal point and ensuring that the conductive adhesive film is electrically connected with the metal point

### FIG. 3, amend the description in step 306 as follows:

aligning the points to be tested on the [[print]] <u>printed</u> circuit board with the protruding metal points

# FIG. 3, amend the descriptions in step 307 as follows:

using the pressure from the press of the tester and tests to electrically connect the metal points and points to be tested on the [[print]] printed circuit board to the conductive

Serial Nr.: 10/627,837 03177-URS

Art Unit: 3729

# rubber adhesive film